



NOTES:

1. A SIDEWALK TRIP HAZARD EXISTS IF THERE IS A VERTICAL HEIGHT DIFFERENCE BETWEEN ADJACENT SIDEWALK PANEL SECTIONS.
2. IF THE SIDEWALK IS RAISED NOT MORE THAN ONE (1) INCH AND THE CONCRETE EDGES ARE SOLID, THE CONCRETE MAY BE GROUND TO REMOVE THE TRIP HAZARD.
3. FOR A TRIP HAZARD OF $\frac{1}{2}$ ", GRIND BACK A MINIMUM OF SIX (6) INCHES.
4. FOR A TRIP HAZARD OF BETWEEN $\frac{1}{2}$ " AND 1", GRIND BACK A MINIMUM OF TWELVE (12) INCHES.
5. FOR A TRIP HAZARD OF MORE THAN 1", REMOVE AND REPLACE ENTIRE PANEL IN ACCORDANCE WITH DWG NO. 250.



**CITY OF HAPPY VALLEY
ENGINEERING DIVISION**
16000 SE MISTY DRIVE
HAPPY VALLEY, OR 97086

DWG NO: 255

CITY ENGINEER
CAROL EARLE, P.E.

SIDEWALK TRIP HAZARD

DATE: 4/1/2019

REVISED BY: PCB/JHH